



HOGEN INDUSTRIES, INC.
OF INDIANA
4655 Massachusetts Avenue
Indianapolis, IN 46218
800-912-4123
Fax: 317-591-5071

MATERIAL SAFETY DATA SHEET

ISSUED DATE 11-15-85 REVISED DATE 9-30-09

I. IDENTIFICATION

MANUFACTURER'S NAME		Hogen Industries, Inc..		EMERGENCY TELEPHONE NO.		(317) 591-5070	
ADDRESS		4655 Massachusetts Avenue - Indianapolis, IN 46218					
CHEMICAL NAME AND SYNONYMS		Tungsten, Copper		TRADE NAME AND SYNONYMS		H10W	
C.A.S. NO.		NIF		T.S.C.A. NO.		NIF	
				FORMULA		W-Cu	
DEPARTMENT OF TRANSPORTATION	HAZARD CLASSIFICATION	NIF		U.N. NO.		NIF	
	SHIPPING NAME	H10W COPPER TUNGSTEN					

II. INGREDIENTS

MATERIAL	%	TLV (Units)	C.A.S. NO.	NFPA RATING 4 = EXTREME 3 = HIGH 2 = MODERATE 1 = SLIGHT 0 = INSIGNIFICANT
Tungsten	75	5 MG/M ³	7440-33-7	
Copper	25	1 MG/M ³	7440-50-8	

REPORT ALL INGREDIENTS ≥3%; IF HAZARDOUS, REPORT ≥1%; SPECIAL HAZARDOUS SUBSTANCES ≥0.01%

III. PHYSICAL DATA

BOILING POINT, 760mm Hg 101.325 kPa	Tungsten - 5660°C Copper - 2567°C	FREEZING POINT	N/A
SPECIFIC GRAVITY (H ₂ O=1)	14.70 g/cc	VAPOR PRESSURE AT 20°C	N/A
VAPOR DENSITY (AIR=1)	N/A	SOLUBILITY IN WATER, % BY WT.	N/A
APPEARANCE AND ODOR	Copper Colored - No odor		

IV. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method Used)	NIF	FLAMMABLE LIMITS LEL	NIF	UEL	NIF
EXTINGUISHING MEDIA	NIF (No Information Found)				
SPECIAL FIRE FIGHTING PROCEDURES	NIF				
UNUSUAL FIRE AND EXPLOSION HAZARDS	Will oxidize above 1300°F				

V. REACTIVITY DATA

STABILITY		CONDITIONS TO AVOID	Nitric Acid will cause oxidation of the copper and form Nitrogen Oxide. Avoid other strong acids.
UNSTABLE	STABLE		
	X		

INCOMPATIBILITY (Materials to Avoid)	
HAZARDOUS DECOMPOSITION PRODUCTS	

VI. HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE	OSHA Tungsten 5 MG/M ³ Copper 1 MG/M ³	ACGIH Tungsten 5 MG/M ³ Copper 1 MG/M ³	
ROUTES OF EXPOSURE (Check Those Which Apply)	EYE CONTACT No	INHALATION No	SKIN ABSORPTION No
	SKIN CONTACT No	INGESTION No	
SIGNS AND SYMPTOMS OF OVEREXPOSURE	NIF (No Information Found)		
EFFECTS OF OVEREXPOSURE			
ACCUTE	NIF		
CHRONIC	NIF		
HAS IOSHA FOUND THIS MATERIAL TO BE A POTENTIAL CARCINOGEN?	YES	NO	X
EMERGENCY FIRST AID PROCEDURES			

VII. SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELATED OR SPILLED	
WASTE DISPOSAL METHOD	Re-cycle all scrap and machine turnings.
	DISPOSER MUCH COMPLY WITH FEDERAL, STATE AND LOCAL DISPOSAL OR DISCHARGE LAWS.

VIII. SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify Type)	Use NIOSHA/MSHA approved type respirator for dusting conditions		
VENTILATION	LOCAL EXHAUST	Recommended	SPECIAL NIF
	MECHANICAL (General)	NIF	OTHER NIF
PROTECTIVE GLOVES	None	EYE PROTECTION	Use safety eyewear
OTHER PROTECTIVE EQUIPMENT	None		

IX. SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	Store in cool, dry, well ventilated area. Separate from acids and alkalis.
OTHER PRECAUTIONS	

DISCLAIMER OF LIABILITY

As the conditions or methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of the material. Information contained herein is believed to be true and accurate but all statements or suggestions are made without any warranty, express or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof.