



**HOGEN INDUSTRIES, INC.**  
OF INDIANA  
4655 Massachusetts Avenue  
Indianapolis, IN 46218  
800-912-4123  
Fax: 317-591-5071


# MATERIAL SAFETY DATA SHEET

ISSUED DATE 11-06-91 REVISED DATE 9-30-09

## I. IDENTIFICATION

MANUFACTURER'S NAME		Hogen Industries, Inc.		EMERGENCY TELEPHONE NO.		(317) 591-5070	
ADDRESS		4655 Massachusetts Avenue - Indianapolis, IN 46218					
CHEMICAL NAME AND SYNONYMS		Tungsten, Nickel, Iron		TRADE NAME AND SYNONYMS		HM1150	
C.A.S. NO.	NIF	T.S.C.A. NO.	NIF	FORMULA	NIF		
DEPARTMENT OF TRANSPORTATION	HAZARD CLASSIFICATION	NIF		U.N. NO.	NIF		
	SHIPPING NAME	HM1150 Tungsten Alloy					

## II. INGREDIENTS

MATERIAL	%	TLV (Units)	C.A.S. NO.	NFPA RATING 
Tungsten	92.5	5 MG/M <sup>3</sup>	7440-33-7	
Nickel	5.25	1.0 MG/M <sup>3</sup>	7440-02-0	
Iron	2.25	5 MG/M <sup>3</sup>	7439-89-6	

4 = EXTREME  
3 = HIGH  
2 = MODERATE  
1 = SLIGHT  
0 = INSIGNIFICANT

REPORT ALL INGREDIENTS ≥3%; IF HAZARDOUS, REPORT ≥1%; SPECIAL HAZARDOUS SUBSTANCE ≥0.01%

## III. PHYSICAL DATA

BOILING POINT, 760mm Hg 101.325 kPa	W - 5660°C, Ni - 2732°C Fe - 3000°C	FREEZING POINT	N/A
SPECIFIC GRAVITY (H <sub>2</sub> O=1)	17.5 g/cc	VAPOR PRESSURE AT 20°C	N/A
VAPOR DENSITY (AIR=1)	N/A	SOLUBILITY IN WATER, % BY WT.	Insoluble
APPEARANCE AND ODOR	Gray, Silver - No odor.		

## IV. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method Used)	Non-combustible	FLAMMABLE LIMITS LEL	N/A	UEL	N/A
EXTINGUISHING MEDIA	Dry Type				
SPECIAL FIRE FIGHTING PROCEDURES					
UNUSUAL FIRE AND EXPLOSION HAZARDS	Will oxidize at or above 1300°F.				

## V. REACTIVITY DATA

STABILITY			
UNSTABLE	STABLE	CONDITIONS TO AVOID	There is some evidence that Nickel and certain Nickel Compounds are carcinogenic to humans. Metallic Nickel seems to be less likely than Nickel Sulfide or Nickel Oxides.
	X		
INCOMPATIBILITY (Materials to Avoid)			
HAZARDOUS DECOMPOSITION PRODUCTS		Keep away from strong acids.	

## VI. HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE	OSHA	Tungsten 5 MG/M <sup>3</sup> Nickel 1.0 MG/M <sup>3</sup> Iron 5.0 MG/M <sup>3</sup>	ACGIH	Tungsten 5 MG/M <sup>3</sup> Nickel 1.0 MG/M <sup>3</sup> Iron 5.0 MG/M <sup>3</sup>
ROUTES OF EXPOSURE (Check Those Which Apply)	EYE CONTACT	No	INHALATION	No
	SKIN CONTACT	No	INGESTION	No
SIGNS AND SYMPTOMS OF OVEREXPOSURE NIF ( No Information Found)				
EFFECTS OF OVEREXPOSURE				
ACCUTE NIF				
CHRONIC NIF				
HAS IOSHA FOUND THIS MATERIAL TO BE A POTENTIAL CARCINOGEN? YES NO X				
EMERGENCY FIRST AID PROCEDURES				

## VII. SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELATED OR SPILLED	
WASTE DISPOSAL METHOD	Recycle scrap and machine turnings.
DISPOSER MUCH COMPLY WITH FEDERAL, STATE AND LOCAL DISPOSAL OR DISCHARGE LAWS.	

## VIII. SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify Type)	Use NIOSHA/MSHA approved type respirator for dusting conditions.		
VENTILATION	LOCAL EXHAUST	Recommended	SPECIAL NIF
	MECHANICAL (General)	NIF	OTHER NIF
PROTECTIVE GLOVES	NIF	EYE PROTECTION	Use safety eyewear.
OTHER PROTECTIVE EQUIPMENT	NIF		

## IX. SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	Store in cool, dry, well ventilated area. Separate from acids and alkalis.
OTHER PRECAUTIONS	

### DISCLAIMER OF LIABILITY

As the conditions or methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of the material. Information contained herein is believed to be true and accurate but all statements or suggestions are made without any warranty, express or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof.

Form # 137

Rev. B  
03/01/06  
Page 2 of 2